

### General

Transparent ROTEC® ABS can generally be processed using all techniques convenient for thermoplastic resins. In particular they can be easily moulded on usual injection moulding machines. Due to the balanced processing properties and their excellent thermal stability, injection moulded parts with superb surface finish and gloss can be easily produced from all transparent ROTEC® ABS grades. Basically all usual types of gates can be used (VDI 2006).

At processing of transparent ROTEC® ABS all screws and dosing elements have to be cleaned well, as already smallest traces of pollution can affect surface brilliance and IR-permeability is impaired.

### Storage

Transparent ROTEC® ABS should be stored dry in closed rooms and protected from direct sun light. When stored on open areas, the package may be damaged thereby the physical and optical properties may be impaired.

### Drying

Transparent ROTEC® ABS leaves the production facility with a residual moisture content level of < 0.3 %. This value is controlled using the moisture analyzer (Aquatrac). We recommend to dry the material up to a moisture content < 0.05 %.

Under adverse transport and storage conditions all transparent ROTEC® ABS can absorb moisture so that surface defects such as streaks can appear. Before processing we strongly recommend to pre-dry transparent ROTEC® ABS for 2 – 4 hours at a temperature of 80 °C ( $\pm 5$  °C) in a dry air dryer. These dry the materials with high reliability even at high outside humidity.

We recommend cleaning the dryer and transport containers thoroughly before drying to avoid possible contamination, otherwise transparency respectively IR permeability cannot be guaranteed.

The above processing guidelines should advise without commitment. The statements given are based on our experience and are correct to the best of the knowledge at the time of printing, but the actual applications and processes are beyond our sphere of influence. No liability should be assumed as a result of this information.

# PROCESSING GUIDELINES INJECTION MOLDING

## transparent ROTEC® ABS

**ROMIRA**

### Processing

The processing conditions should be selected depending on the injection moulding machine and the size or shape of the finished parts. The parameters listed below are used to support the established injection moulding properties. Of particular note is the melt temperature if using hot runner. Following conditions are recommended for processing:

ROTEC® ABS	Transparent
Drying temperature	80 ± 5 °C
Drying time	2 – 4 h
Barrel temperature	210 – 250 °C
Tool temperature	40 – 80 °C
Injection speed	high
Melt temperature	< 260 °C
Pheripheral screw speed	0.25 to 0.3 m/s
Back pressure	low

The above mentioned processing parameters are only approximants and depend on the tool geometry and the machine used.

Transparent ABS is milky-white when warm and is getting transparent at room temperature.

### Recycling

Previous tests before recycling of rejected parts, gates etc. from transparent ROTEC® ABS are recommended. It should be considered that the regrind is free of dust. Due to reprocessing conditions the small dust particles from grinding process can burn, thus can influence the technical and optical values and lead to "black specs".

**For special requirements at finished parts (e.g. IR-permeability), only original material should be used.**

The above processing guidelines should advise without commitment. The statements given are based on our experience and are correct to the best of the knowledge at the time of printing, but the actual applications and processes are beyond our sphere of influence. No liability should be assumed as a result of this information.